

# 314

# BG Full Synthetic ATF APPLICATION CHART

BG Full Synthetic ATF, PN 314, meets or exceeds the performance requirements of the following automatic transmission fluids.

MAKE	ATF PN
<b>Acura</b>	ATF-Z1
<b>Aisin Warner</b>	AW-1
<b>Alfa Romeo</b>	ALL
<b>Allison</b>	C-3, C-4, John Deere HD SynTran, <sup>™</sup> Mobil Delvac Synthetic ATF <sup>™</sup>
<b>American Motors</b>	ATF+3 (MS-7176E), +4 (MS-9602)
<b>Aston Martin</b>	ALL
<b>Audi</b>	G052025A2, G052162A1, G052162A2, LT71141, G055025A2, G052990A2, G055005A2, G055005A6, G055162A2
<b>Bentley</b>	NONE
<b>BMW</b>	LA2634, LT71141, 81229400275, 83220403248, 83220403249, 83229407765, 83227542290, 83229407807, 83220024359, 83220026922, BMW807, TEXACO ETL-7045E, TEXACO ETL-8072B, 705/ATFD-3, 83220402413, 83220397114, 83222163514, 83222355599
<b>Caterpillar</b>	TO-2
<b>Chrysler/Mopar</b>	ATF 7176, +2, +3 (MS-7176E), +4 (MS-9602), AS68RC, 05189966AA, 05189977AA, 05189977AB, 05127382AA, 05127382AB, 68171866, 68171866AB, 68171869AB
<b>Citroen</b>	973622, Z000169756
<b>Daewoo</b>	LT71141
<b>Daihatsu:</b>	AMMIX ATF-DII, AMMIX ATF-DIII
<b>Diwa</b>	55.6335.XX (G 607), 55.6336.XX (G1363)
<b>Esso</b>	ATF LT 71141
<b>Fiat-Lancia</b>	ALL
<b>Ford</b>	MERCON <sup>®</sup> (XT-2-QDR OR XT-2-QSM), MERCON <sup>®</sup> SP (XT-6-QSP), MERCON <sup>®</sup> V (XT-5-QM), MERCON <sup>®</sup> LV(XT-10-QLV), PREMIUM AUTOMATIC TRANSMISSION FLUID (XT-8-QAW), FNR5 AUTOMATIC TRANSMISSION FLUID (XT-9-QMM5), X-2-QDX
<b>Fuso</b>	ATF-II, ATF-SPIII
<b>General Motors</b>	DEXRON <sup>®</sup> , DEXRON <sup>®</sup> -II, -IID, -IIE, -III, -IIIG/H, DEXRON <sup>®</sup> -VI, GM T-IV (PN 88900925), 9986195, 93160393, 22717466
<b>Honda</b>	ATF-Z1
<b>Hyundai</b>	SP-II, SP-III, SP-IV, SPH-IV
<b>Idemitsu</b>	K17, JATCO 3100 PL085, W0133-19031-54
<b>Infiniti</b>	MATIC D, J, K, S
<b>Isuzu</b>	ATF-II, ATF-III, ATF-SP, 08200-9001
<b>Jaguar</b>	ATF 3403 M115, 1X43 2C9010AA, JLM 20237, JLM 20238, JLM 20292, LT71141, JATCO 3100 PL085
<b>Jeep</b>	SEE CHRYSLER/MOPAR
<b>JWS</b>	3309, 3324
<b>Kia</b>	SP-II, SP-III, SP-IV, RED 1, RED 1K, UM090-CH042 (TYPE 4 SP-IV)
<b>Land Rover</b>	ESSO LT71141, TEXACO N402, ETL-7045E
<b>Lexus</b>	Type T, T-II, T-III, T-IV, WS
<b>Man</b>	339F, 339V1, 339V2, 339Z1, 339Z2, 339Z3
<b>Maserati</b>	NONE
<b>Matra</b>	ALL
<b>Mazda</b>	ATF-M III, ATF-MV, 0000-77-112E-01, 0000-77-120E-05, 0000-77-114E-01

**MAKE ATF PN**

---

<b>Mercedes Benz</b>	236.1, 236.2, 236.3, 236.5, 236.6, 236.7, 236.9, 236.10, 236.11, 236.12, 0019892103, SHELL 3403-4 115, A0019892203, 0019894503, 0019896803*
<b>Mitsubishi</b>	DIAMOND SP, SP-II, SP-III, SP-IV, J2, J3
<b>Nissan</b>	MATIC D, J, K, S
<b>Opel</b>	1940700, 1940767, 1940771, 2217466, 88900925, 9986195
<b>Peugeot</b>	973622, Z000169756
<b>Porsche</b>	99991754700A2, 00004320509, 00004320441, SHELL 3403 M115, 99991754700, 000 043 205 28, Z000169756
<b>Renault</b>	7711218368
<b>Rolls Royce</b>	PL31493 PA
<b>Saab</b>	93160372, 93160393, 93165147
<b>Saturn</b>	22689186
<b>Shell</b>	LA2634, ATF 3353, ATF 3403 M115
<b>Subaru</b>	SOA868V9241, K0140Y0700, HP/PS SOA427V1500, SOA868V9240, ATF-HP
<b>Suzuki</b>	99980-06000, ATF 3317 SP-4B, 990B0B-01001, ATF 3314
<b>Texaco</b>	ETL-7045E, ETL-8072B, N402
<b>Toyota</b>	TYPE T, T-II, T-III, TYPE T-IV, TOYOTA WS
<b>Voith</b>	55.6335.XX (G607), 55.6336.XX (G1363)
<b>Volvo</b>	97325, 97335, 97340, 97341, 3344208, 31256774, 31256775, 31256776, 1161521, 1161540, 1161640, 1161621
<b>Volkswagen</b>	G055025A2, G052162A2, G052990A2, G052025A2, G052162A1, LT71141, G055005A2, G055005A6, G055162A2
<b>ZF Friedrichshafen AG</b>	TE-ML: 02F, 03D, 04D, 05L, 09, 11A, 11B, 14A, 14B, 14C, 16L, 17C, 21L, SHELL LA 2634, LT 71141

**BG Full Synthetic ATF is not recommended for use in the following applications:**

Acura DW-1, TYPE 3.0 PN 08200-9016A, TYPE 2.0 PN 08200-9015A, TYPE 3.1 PN 08200-9017A  
AC Delco® Dexron® ULV PN 10-4107  
Audi G060162A2, G055540A2  
BMW 83220142156, 83220142516, 83222152426, 83222220445, 83222289720, 83222220443, 83222305396  
Chrysler/Mopar 68157995AA, 68157995AB, 68218925AA  
Continuously Variable Transmissions (CVTs)  
Dual Clutch Transmissions (DCTs)  
Direct-Shift Gearbox (DSG)  
Ford Type F, Ford MERCON® ULV, XT-12-QULV  
GM DEXRON®-HP  
Hyundai 040000C90SG, NWS-9638, SPH-IV-RR, 00232-19015, 00232-19016, SP4-M, 00232-19057, 00232-19059, NWS-9638 T5, 00232-19052  
Honda DW-1, TYPE 3.0 PN 08200-9016A, TYPE 2.0 PN 08200-9015A, TYPE 3.1 PN 08200-9017A  
Kia ATF TYPE 4(M)  
Jaguar C2C8432, JDE 26444  
Land Rover TYK500050, LRN 13754, LR 023288, LR 023289  
Maserati 231603  
Mazda ATF-FZ, 0000-FZ-113E-01  
Mercedes-Benz 236.14, 236.15, 236.16, 236.17, 236.41, ATF 4134  
All Mercedes Benz 722.9 transmissions built after June 21, 2010, requiring ATF A0019897803  
\*All Mercedes Benz 722.9 transmissions built before June 21, 2010, requiring ATF A0019896803  
Motorcraft® MERCON® ULV, PN XT12QULV

Shell M-1375.4, M-1375.5, M-1375.6, M-L12108

Volkswagen G055540A2, G060162A2

ZF-Friedrichshafen AG TE-ML: LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281),  
Life Guard Fluid 8 (AA00601304)

**BG Products, Inc., accepts no liability for excessive use or misuse of this product.**

**Revision date** 8-20-20

**Revisions** **Added to Hyundai section**  
- SPH-IV, SP-IV  
**Added to Kia section**  
- UM090-CH042 (TYPE 4 SP-IV)  
**Removed from “Not Recommended” section**  
- HYUNDAI SPH-IV  
- KIA SP-IV, UM090-CH042 (TYPE 4 SP-IV)

**8-10-20** **Added to Hyundai section**  
- SP-IV  
**Removed from “Not Recommended” section**  
- HYUNDAI AND KIA

**6-10-20** **Updated “Not Recommended” section**  
- ADDED “MOTORCRAFT® MERCON® ULV PN XT12QULV”  
- ADDED “ACDELCO® DEXRON™ ULV P/N 10-4107”

**4-27-20** **Updated on Chrysler/Mopar section**  
- 05189977AB  
- 68171866AB

**3-30-20** **Added to KIA section**  
- SP-IV

**10-29-19** **Added to American Motors section**  
- ATF +3 (MS-7176E), +4 (MS-9602)  
**Added to BMW section**  
- 83227542290  
-Changed ELT to ETL  
**Added to Chrysler/Mopar section**  
- 05127382AB  
**Removed from Daewoo section**  
- Removed “ALL INCLUDING”  
**Added Daihatsu section**  
- AMMIX ATF-DII, AMMIX ATF-DIII  
**Added to Diwa section**  
- 55.6335.XX (G 607), 55.6336.XX (G1363)  
**Added Fuso section**  
- ATF-II, ATF-SPIII  
**Added to General Motors section**  
- 93160393, 22717466  
**Removed from Infiniti section**  
- Removed “ALL INCLUDING”  
- Removed “AND”  
**Added to Isuzu section**  
- ATF-II, ATF-III, ATF-SP, 08200-9001  
-Removed “ALL”

**10-29-19 Added to Jaguar section**

- JLM 20292

**Added to Kia section**

- Red 1K

**Added to Lexus section**

- Type T, T-II, T-III, T-IV, WS

- Removed "ALL"

**Added to Opel section**

- 1940700, 1940767, 1940771, 2217466, 88900925, 9986195

- Removed "ALL"

**Added to Porsche section**

- Z000169756

**Removed from Saturn section**

- Removed "ALL"

**Added to Subaru section**

- HP/PS

**Added to Suzuki section**

- ATF 3314

**Added to Volvo section**

- 97325

- 97335

**Added to ZF Friedrichshafen AG section**

- 05L

- 21L

**Edits in "Not recommended" section**

Added Acura section

- DW-1, TYPE 3.0 PN 08200-9016A, TYPE 2.0 PN 08200-9015A, TYPE 3.1 PN 08200-9017A

Added to Audi section

- G055540A2

Added to BMW section

- 83222152426, 83222220445, 83222289720, 83222220443, 83222305396

Chrysler/Mopar section

- Removed 05127382AB

- Added 68157995AA, 68157995AB, 68218925AA

Added to Hyundai section

- NWS-9638, SPH-IV-RR, 00232-19015, 00232-19016, SP4-M, 00232-19057, 00232-19059, NWS-9638 T5, 00232-19052

Added to Honda section

- TYPE 3.0 PN 08200-9016A, TYPE 2.0 PN 08200-9015A, TYPE 3.1 PN 08200-9017A

Added Kia section

- SP-IV, UM090-CH042 (TYPE 4 SP-IV), ATF TYPE 4 (M)

Added to Jaguar section

- JDE 26444

Added to Land Rover section

- LR 023288, LR 023289

Added Mazda section

- ATF-FZ, 0000-FZ-113E-01

- 10-29-19 Edits in “Not recommended” section**  
Added to Mercedes-Benz section  
- 236.16, 236.17, 236.41, ATF 4134  
Added to Shell section  
- M-1375.5  
Added to Volkswagen section  
- G055540A2
- 4-18-18 Added to BMW section**  
- 83222355599
- 9-13-17 Added to Not Recommended section**  
- Ford MERCON® ULV, XT-12-QULV
- 12-9-16 Under Ford and GM sections**  
- Removed space after Mercon®  
- Added hyphen after Dexron®
- 5-5-16 Added to Not Recommended section**  
- GM Dexron HP
- 3-17-16 Added this PN to Chrysler/Mopar:**  
- 68171869AB
- 1-5-16 Added to Subaru:**  
- SOA427V1500; SOA868V9240; ATF-HP  
**Added to Infiniti**  
- Nissan Matic S ATF
- 7-13-15 Changed Acura:**  
- REMOVED “ALL” ADDED “ATF-Z1”  
**Removed from Jaguar:**  
- JDE-26444  
**Changed Jeep:**  
- REMOVED “ALL” added “SEE CHRYSLER/MOPAR”
- 6-25-15 Added to Allison:**  
- John Deere HD SynTran™  
- Mobil Delvac Synthetic ATF™
- 5-18-15 Added this PN to Chrysler/Mopar:**  
- 68171866
- 1-18-15 Added this PN to ZF Friedrichshafen AG:**  
- LT 71141
- 11-25-14 Removed the word “ALL” from Subaru:**
- 9-3-14 Removed these ATF PN’s from Allison:**  
- TES-295  
- TES-389
- 8-28-14 Added these ATF PN’s to Volvo:**  
- 31256775  
- 31256776

**6-30-14 Added this ATF PN to Audi & Volkswagen:**

- G055005A2, G055005A6, G055162A2

**Added this to the not recommended list:**

- Dual Clutch Transmissins (DCTs)

**2-20-14 Added this ATF PN to Jaguar:**

- JDE 26444

**2-11-14 Added this ATF PN to BMW:**

- 83222163514

**6-19-13 Removed VW Part Number from Audi Section:**

- G052182A2

**6-12-13 Added this ATF PN to Subaru:**

- K0140Y0700

**Added this ATF PN to Idemitsu:**

- W0133-19031-54

**REMOVED this ATF PN from Volkswagen:**

-G052182A2